



# ALT2079CP

## **TECHNICAL BULLIETIN TB—022**

There are some known faults with the vehicle this alternator fits, causing early life failure

- Commonly known fault with the wiring causing over-charging or warning light on.
- Commonly known fault which cause the premature failure of the alternator clutch pulley or bearings.



[www.rollco.co.uk](http://www.rollco.co.uk)

**+44-1268-271035**  
**info@rollingcomponents.com**