


It is possible that you were supplied with the Hitachi model as shown below for this application. Although this unit appears to be different from the one removed from the vehicle, it is totally compatible and will interchange with the Bosch model below.

**BOSCH MODEL
STM 649**



**HITACHI MODEL
STM303**

