

STARTER HAVING BUSH PROBLEMS

We have been reported problems with Bushes.
We recommend this Starter Motor must be mounted with a new location bush.

Please remove the old bush which could remain in the engine block when you remove the old Starter.

This application is prone to sticking ignition key switch or relay problems. This causes the starter motor to be hold in-mesh whilst the engine is running.

Check the old unit for signs of this problem (see pics) and repair before filling the new starter.



WARRANTY WILL BE REJECTED IN THESE CASES

Please call our Technical team for more information, before submitting RMA request

For information on any specific replacement unit please call our technical department.
Rolling Components Ltd Tel: 00 44(0)1268 271036 Fax: 00 44(0) 1268 527334 / 1268 534476
Or visit our website www.rollingcomponents.com