


Missed Dowel

STM926 / STM963 / STM965



These units have a dowel which is located between the starter motor and gearbox. This allows for the unit to be aligned in the correct position. When removing the old starter motor please make sure the dowel either comes out with the old unit or removed from the gearbox and refitted to the new starter motor. If you fail to do this the unit will not align properly and will cause the unit to be very noisy or fail prematurely. If you don't follow this warning your warranty maybe void.

**Please call our Technical team for more information
before submitting RMA request**

For information on any specific replacement unit please call our technical department.

Rolling Components Ltd

Tel: 00 44(0)1268 271036 Fax: 00 44(0) 1268 527334 / 1268 534476

Or visit our website www.rollingcomponents.com