

## OIL AND WATER INGRESS

WE HAVE MANY STARTER MOTORS AND ALTERNATORS RETURNED WITH OIL, WATER AND DIESEL INGRESS. PLEASE CHECK YOUR OLD UNIT FOR SIGNS OF THIS AND IF NECESSARY REPAIR THE PROBLEM BEFORE FITTING THE NEW UNIT PREVENTING EARLY LIFE FAILURE.

THIS MIGHT CAUSE YOUR WARRANTY TO BE VOID



**\*Please Note - STM511/ STM525-** These starters motors have several version that all interchange with each other even though they have different amount of teeth on the drive. These manufactures are either **Bosch, Valeo or Mistubishi**. It may cause concern when coming to fit these units but they do all interchange. The only important is the pitch not the number of teeth or size of the drive.